

20000801.ba v02_n959.bam.20000801

>From ???@??? Tue Aug 1 00:01:16 2000 -0500
Message-Id: <200008010500.e7150fb16621@sco.theporch.com>
Date: Tue, 1 Aug 2000 00:00:22 CDT
From: Old Tube Radios <boatanchors@theporch.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: BOATANCHORS digest 2959

BOATANCHORS Digest 2959

Topics covered in this issue include:

- 1) 26A6/C6/A7 tube source needed
by Bob Login <jlogin@mindspring.com>
- 2) Drake R4B on 30 meters
by Niel Wiegand <nielw@ix.netcom.com>
- 3) RE: WW2 microphone?
by "ROBERT W. DOWNS" <RWDowns_WA5CAB@compuserve.com>
- 4) Morrow FTR and 5BRF and Power Supply Help Needed
by Matt Jodziewicz <mattj@oraus.com>
- 5) HT-32B Parts needed
by "Jim Reynolds" <ki6up@earthlink.net>
- 6) APA-2 Power Supply
by "Jim Reynolds" <ki6up@earthlink.net>
- 7) Re: APA-2 Power Supply
by William Donzelli <aw288@osfn.org>
- 8) Morrow FTR / 5BRF and PS Help Needed
by Matt Jodziewicz <mattj@oraus.com>

Message-Id: <3.0.1.32.20000731093650.00824630@pop.mindspring.com>
Date: Mon, 31 Jul 2000 09:36:50 -0400
To: Old Tube Radios <boatanchors@theporch.com>
From: Bob Login <jlogin@mindspring.com>
Subject: 26A6/C6/A7 tube source needed
Mime-Version: 1.0
Content-Type: text/plain; charset="us-ascii"

Hi Fellow Collectors:

I just bought a R392 with some weak or shorted 26 series tubes.
Fair sells some are there other sources?...73 & Tnx Bob, AA8A

Message-ID: <39860870.C571B723@ix.netcom.com>
Date: Mon, 31 Jul 2000 18:14:56 -0500
From: Niel Wiegand <nielw@ix.netcom.com>

MIME-Version: 1.0
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Drake R4B on 30 meters
Content-Type: text/plain; charset=us-ascii
Content-Transfer-Encoding: 7bit

I just tried my Drake R4B on 30 meters and find I have an S9 birdie at 10.104MHz.

Anyone else with the same problem? Fix?

73, Niel, W0VLZ

Date: Mon, 31 Jul 2000 19:38:08 -0400
From: "ROBERT W. DOWNS" <RWDowns_WA5CAB@compuserve.com>
Subject: RE: WW2 microphone?
To: Old Tube Radios <boatanchors@theporch.com>
Message-ID: <200007311938_MC2-AE10-6E96@compuserve.com>
MIME-Version: 1.0
Content-Transfer-Encoding: quoted-printable
Content-Type: text/plain;
 charset=ISO-8859-1
Content-Disposition: inline

Mike, Marty & Group,

The microphone that both of you have was to the Navy what the T-17-(*) was to the Army and AAC. How it was marked seems to depend upon which contractor made it. The generic description would be single-button carbon microphone with PTT, straight or coiled cord, and standard military microphone connector (PL-68 or N.A.F. 212938-1). As an aside, why do some people think of this plug as a "Collins" type? Of the millions made, only a few thousand came from Collins.

Anyway, the NT-51004 was made by several contractors, including Magnavox (CMX) and Telephonics (CTE), and in revisions up to CMX or CTE-51004-C. =

Nomenclature molded into the case may be Cxx-51004-a, N.A.F. 212264-6, RS-38-(*), or I've learned recently that they were also made for the RAF with yet a different set of numbers molded in. For the most part, those that do not have Cxx-51004-a molded into the case have it stamped on a metal tag wrapped around the cord (including those made for the RAF). This is

microphone was used with many Navy sets, including the TBX and TCS. A variant was also used with the TBY and MAB. It has more contacts on the PTT switch, and more holes in the front than the three normally found on the 51004. =

73,
Robert Downs
WA5CAB
Houston

Message-ID: <30AB00986E91D211A08B00104B8942F0235065@ORAMAIL>
From: Matt Jodziewicz <mattj@oraus.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Morrow FTR and 5BRF and Power Supply Help Needed
Date: Mon, 31 Jul 2000 13:30:01 -0700
MIME-Version: 1.0
Content-Type: multipart/alternative;
boundary="----_=_NextPart_001_01BFFB2E.1F18E5F0"

This message is in MIME format. Since your mail reader does not understand this format, some or all of this message may not be legible.

-----_=_NextPart_001_01BFFB2E.1F18E5F0
Content-Type: text/plain;
charset="iso-8859-1"

Subject says it all. Picked up a pretty little Morrow Fixed Tuned Radio and Converter from a TRW swap table but need a manual or any help on what the Power Supply would be like (so I can build one). The radio is really a neat looking little rig and I would like to get it working if at all possible as the actual insides are pristine from 1956!!

Thanks for any help.

Matt WB2VZS

-----_=_NextPart_001_01BFFB2E.1F18E5F0
Content-Type: text/plain; charset=us-ascii
Content-Transfer-Encoding: 7bit

* * * * *
* ---REMAINDER OF MESSAGE TRUNCATED--- *
* This post contains a forbidden message format *
* (such as an attached file, a v-card, HTML formatting) *
* Mail Lists at theporch.com only accept PLAIN TEXT *
* If your postings display this message your mail program *

* is not set to send PLAIN TEXT ONLY and needs adjusting *

-----_=_NextPart_001_01BFFB2E.1F18E5F0--

From: "Jim Reynolds" <ki6up@earthlink.net>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: HT-32B Parts needed
Date: Mon, 31 Jul 2000 21:37:09 -0500
Message-ID: <000b01bffb61\$63eae080\$694afc9e@ripcord>
MIME-Version: 1.0
Content-Type: text/plain;
 charset="iso-8859-1"
Content-Transfer-Encoding: 7bit

Hello Gang,

Well, I have narrowed my problems down to the transformer in the HT-32B.

Also, the heater resistor, r-66 is toasted.

I would like a replacement transformer, or a parts rig with one in it. (a HT-32 in good shape would be a idea, and keep this one for parts??)

I need a heater resistor

I have wanted one of these rigs for a long time - and any help would be appreciated.

73
Jim
KI6UP

From: "Jim Reynolds" <ki6up@earthlink.net>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: APA-2 Power Supply
Date: Mon, 31 Jul 2000 22:03:27 -0500
Message-ID: <000d01bffb65\$104095c0\$694afc9e@ripcord>
MIME-Version: 1.0
Content-Type: text/plain;
 charset="iso-8859-1"
Content-Transfer-Encoding: 7bit

I have a APA-2 Power supply, rack mount and looks like it could be military.
3 meters across the front -

heater voltage - plate current - plate voltage
and each has a pot to set the values for each (I think)

Has any one ever heard of one of these?

73

Jim

KI6UP

Date: Mon, 31 Jul 2000 23:13:22 -0400 (EDT)
From: William Donzelli <aw288@osfn.org>
To: Old Tube Radios <boatanchors@theporch.com>
cc: Old Tube Radios <boatanchors@theporch.com>
Subject: Re: APA-2 Power Supply
Message-ID: <Pine.SUN.3.91-FP.1000731231235.25592H-1000000@osfn.org>
MIME-Version: 1.0
Content-Type: TEXT/PLAIN; charset=US-ASCII

> I have a APA-2 Power supply, rack mount and looks like it could be military.
> 3 meters across the front -
> heater voltage - plate current - plate voltage
> and each has a pot to set the values for each (I think)

What does the datatag say?

William Donzelli
aw288@osfn.org

Message-ID: <30AB00986E91D211A08B00104B8942F0235058@ORAMAIL>
From: Matt Jodziewicz <mattj@oraus.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: Morrow FTR / 5BRF and PS Help Needed
Date: Mon, 31 Jul 2000 10:58:46 -0700
MIME-Version: 1.0
Content-Type: multipart/alternative;
boundary="----_=_NextPart_001_01BFFB18.FDEF3710"

This message is in MIME format. Since your mail reader does not understand
this format, some or all of this message may not be legible.

-----_=_NextPart_001_01BFFB18.FDEF3710
Content-Type: text/plain;
charset="iso-8859-1"

Subject says it all. Picked up a pretty little Morrow Fixed Tuned Radio and Converter from a TRW swap table but need a manual or any help on what the Power Supply would be like (so I can build one). The radio is really a neat looking little rig and I would like to get it working if at all possible as the actual insides are pristine from 1956!!

Thanks for any help.

Matt WB2VZS

-----=_NextPart_001_01BFFB18.FDEF3710
Content-Type: text/plain; charset=us-ascii
Content-Transfer-Encoding: 7bit

```
* * * * *
*      ---REMAINDER OF MESSAGE TRUNCATED---      *
*      This post contains a forbidden message format      *
*      (such as an attached file, a v-card, HTML formatting) *
*      Mail Lists at theporch.com only accept PLAIN TEXT      *
*      If your postings display this message your mail program *
*      is not set to send PLAIN TEXT ONLY and needs adjusting *
* * * * *
```

-----=_NextPart_001_01BFFB18.FDEF3710--

End of BOATANCHORS Digest 2959
